

# Conversion/retrofit Crafter (MY 2025 ->)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofitting of rigid tow hitch (for vehicles with preperation from factory)	free	1D7 or 1D8	1D1	33D05	For vehicles <b>up to</b> production date week 10/2025, please note TPI 2077247/*.
Retrofitting of rigid tow hitch (for vehicles without preperation from factory)	88,00 €	1D0	1D1	33D19	For <b>all</b> vehicles, please note TPI 2078334/* . The diagnostic address (0069) for the tow hitch control unit must be identified manually after starting the diagnosis.
Downgrade of rigid tow hitch	88,00 €	1D1	1D7	33CD2	
Retrofitting of rear step (on the right side)	62,00 €	QT5	QT9	34201	Only possible for type 7C0 with tow bar (PR no. 1D1 or 1D8)
Downgrade of rear step	62,00 €	QT4 or QT9	QT5	355E0	
Retrofitting of roof turn indicators	62,00 €	9H0	9H1	343BC	
Downgrade of roof turn indicators	62,00 €	9H1 or 9H2	9H0	34398	
Downgrade 3rd brake light	62,00 €	8R6	8R0	18R07	Only possible for type 7CP.
Retrofitting 3rd brake light	62,00 €	8R0	8R6	357CE	Only possible for type 7CP.
Retrofit SBBR luminaires with LED technology	62,00 €	8SA or 8SE or 8SY	8SX	35257	Only possible for type 7CP. To be used when SBBR luminaires are installed using LED technology.
Downgrade TCO	62,00 €	9NI or 9NC	9NW or 9NL	3408B	The measure code must be used after the tachograph has already been disconnected from the vehicle. After the vehicle has been recoded online with the measure code, the adjustment "tachograph" in the instrument cluster (diagnosis address 17) via the vehicle selfdiagnosis from "installed" to "not installed" must be changed.

# Conversion/retrofit Crafter (MY 2025 ->)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofitting TCO	free	9NW or 9NL	9NI or 9NC	368FF	The diagnostic address (0060) for the TCO must be identified manually after starting the diagnosis.
Retrofitting DAB+	125,00 €	QV0	QV3	1QV31	