Fitting Instructions

Genuine activation "App-Connect"   5H0 054 830 / 5H0 054 830 A
                                                    2K7 054 830 / 2K7 054 830 A

Items supplied:
• 1 x activation document
• 1 x fitting instructions

Special tools, testers, measuring instruments and auxiliary items required:
• Vehicle diagnostic tester with Odis Baseline 9.x version 2.45.4
• Battery charger -VAS 590X-

Procedure:

ⓘ **Note**
• The software update must be carried out by a specialist workshop. Supplementary, vehicle-specific literature may be required. Improper handling can lead to damage to the vehicle.
• Ensure that the no-load voltage of the vehicle battery is at least 12.5 Volt. Connect a battery charger -VAS 590X- to maintain the onboard power supply during the process.
• The software update requires the activation code, the activation number and the activation pin. These details are located on the supplied activation document.
• Changes and amendments to technical specifications is reserved.

– Connect vehicle diagnostic tester to diagnostic connection of vehicle after making sure ignition has been switched off.
– Switch on ignition.
– Start diagnostics and identify vehicle.
– After reading the control units change to "Test plan" and select "Own test".
– Select "Software version management" then testing "Function Activation System" (FFS)" and add test plan using button "Attach test plan".
– Under "Test plan" select "Activate Function System" and click on "Carry out test".
– Then start "Activate function" and chronologically enter: activation code, activation number and activation pin located on activation document. Follow instructions on the vehicle diagnostic tester screen.
– For activation, the online connection is established and the function is activated.

ⓘ **Note**
• If the following **Fault FFP0460E** appears on the ODIS tester after activation, ignore it!
  Check changing PR no.

Carry out following work steps after successfully activating function:

Carrying out software configuration of diagnostic address 005F

– Select "Software version management" then testing "Software configuration of control unit" and add test plan using button "Attach the test plan".
– Under "Test plan" select "Software configuration" and click on "Carry out test".
– Please select:
  1 software configuration (SWK) via diagnostic address => Then enter the diagnostic address: **005F** !
– Check function in vehicle.
– End diagnosis and disconnect connection to vehicle diagnostic tester.
– After successful activation, wait 5 min bus rest (sleep).