

Conversion/retrofit Caddy 5 (MY 2021 ->)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Precondition	New		
Retrofit removable tow hitch	Free	1D7	1D2	364C7	Gateway must be coded manually to "installed" trailer control unit. For using the measure code, the bonnet must be open and the handbrake must not be applied.
Retrofit rigid tow hitch	Free	1D7	1D1	364B3	Gateway must be coded manually to "installed" trailer control unit. For using the measure code, the bonnet must be open and the handbrake must not be applied.
Retrofit removable tow hitch	77,00 €	1D0	1D2	3649F	Gateway must be coded manually to "installed" trailer control unit. For using the measure code, the bonnet must be open and the handbrake must not be applied.
Retrofit rigid tow hitch	77,00 €	1D0	1D1	3648B	Gateway must be coded manually to "installed" trailer control unit. For using the measure code, the bonnet must be open and the handbrake must not be applied.
Removal tow hitch	77,00 €	1D1 or 1D2	1D0	364AF	Gateway must be coded manually to "not installed" trailer control unit. For using the measure code, the bonnet must be open and the handbrake must not be applied.
Retrofit radio incl. hands-free speaking system	280,00 €	8UB and 9W0	I7D and 9ZX	367A8	After recoding using the measure code, the function must be activated on the radio. To do this, please use the guided function "Function activation system (RULT)" in the software version management (SVM).