

Conversion/retrofit Caddy 4 (MY 2016 - 2020)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofit removable tow hitch	86,00 €	1D0	1D2	32F49	Valid for closed and open bodies Trailer stabilisation is activated. Gateway must be coded manually.
Retrofit removable tow hitch	free	1D7	1D2	32F21	Valid for closed and open bodies Trailer stabilisation is activated. Gateway must be coded manually.
Removal removable tow hitch	86,00 €	1D2	1D0	33EC4	Gateway must be coded manually.
Retrofit rigid tow hitch	86,00 €	1D0	1D1	32F61	Valid for closed and open bodies Trailer stabilisation is activated. Gateway must be coded manually.
Retrofit rigid tow hitch	free	1D7	1D1	32F5D	Valid for closed and open bodies Trailer stabilisation is activated. Gateway must be coded manually.
Removal rigid tow hitch	86,00 €	1D1	1D0	330AD	Gateway must be coded manually.
Retrofit fog lights	86,00 €	8WA	8WD	312F3	Only in Medium and Highline BCM
Retrofit fog lights with turning lights	86,00 €	8WA	8WH	312DB	Only in Medium and Highline BCM
Removal fog lights	86,00 €	8WH or 8WD	8WA	31352	
Retrofit turning lights	86,00 €	8WD	8WH	31928	
Removal turning lights	86,00 €	8WH	8WD	31914	
Retrofit twin headlights	86,00 €	8IA	8ID	3165B	

Conversion/retrofit Caddy 4 (MY 2016 - 2020)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofit Xenon headlights	86,00 €	8IA or 8ID or 8IE	8IH	35782	The original headlights (H4 or H7) only need to be replaced with the xenon headlights. For the operation of the xenon headlamp automatic headlamp leveling and headlamp cleaning system is not required, because the luminous flux of the xenon headlamp is less than 2000 lumen. The original, manual headlamp leveling is maintained. Please consider your country-specific law.
Retrofit remote control for independent car heater	61,00 €	7VE	7VL	32ADA	The control and receiver for radio remote control for independent car heater and radio remote control for independent car heater must be retrofitted. Please refer to the picture board 963-020 in the ETKA. For the antenna for the radio remote control for independent car heater, please refer to the picture board 035-028 under "Electrical Connection Elements" in the ETKA.
Retrofitting steering for mobility aid	86,00 €	1N3	1N5	331A0	Power steering for mobility aid in vehicles for people with disabilities After Coding, use the function "Adaption J500 (Charact.curve and all adaptations)" in the guided fault finding
Removal steering for mobility aid	86,00 €	1N5	1N3	315FC	After Coding, use the function "Adaption J500 (Charact.curve and all adaptations)" in the guided fault finding
Retrofit park distance control (PDC)	86,00 €	7X0	7X1	32AEE	Retrofit-set from VW accessories must be used!
Removal park distance control (PDC)	86,00 €	7X1 or 7X7	7X0 or 7X9	34C70	control unit for PDC must be disconnected.
Retrofit rear view camera	86,00 €	7X0, 7X1 or 7X5	7X9, 7X7 or 7X6	33F5F	Only possible on vehicles with tailgate. Only for vehicles with navigation (PR number 7UP) or Radio "Composition Media" (PR number I7A). The retrofit kit of Volkswagen accessories can be used for retrofitting. Please refer to the accessories ETKA.
Retrofit electric window lifters	61,00 €	4R0	4R4	336DB	
Retrofitting electric exterior mirrors	61,00 €	6XA or 6XN	6XE	336C7	Only possible, when electric window lifters are installed. Maybe it is necessary to change the door control units. Please see in the ETKA.
Retrofitting 180A alternator	61,00 €	8GU	8GV	3459E	

Conversion/retrofit Caddy 4 (MY 2016 - 2020)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofit USB for Apple products	61,00 €	UE4 or UI8	UI4 oder UI5	334FD	The USB connection must be renewed including vehicle-sided connecting-housing to an USB connection for Apple products (USB connection 5Q0035726E and vehicle-sided connecting-housing 4E0035750F). The voltage supply via pins 6 and 7 (small, cast-on 2-pin connectors on original wiring connection) must remain intact. Rectify as necessary by workshop means.
Retrofit free-hands speaking system	191,00 €	I7D and 9W0	9ZX	333D2	Only possible with Composition Audio! Microphone was mounted from factory. After coding perform a radio-reset. Push the On-Off button for 20 sec.
Retrofit free-hands speaking system	191,00 €	I6V and 9W0	9ZX	33918	Retrofit for Composition Colour. Microphone must be retrofitted. For the wiring you can use the PN 3G0971140. After coding perform a radio-reset. Push the On-Off button for 20 sec. Information: Only possible for vehicles from model year 2017.
Retrofitting loudspeaker in the rear	86,00 €	8RE	8RL	3368B	
Retrofitting radio "Composition Colour"	61,00 €	I7D	I6V	3541D	You have to replace the radio "Composition Audio" to "Composition Colour". Please see in the ETKA, page 035-000.
Retrofit multifunction steering wheel	86,00 €	1MM or 2PH	2ZH	3531A	The steering-column control unit must be replaced. Please see in the ETKA.
Retrofit DSG shifter at the multifunction steering wheel	61,00 €	2ZH	1XX	3410E	
Retrofit of multifunction control unit	111,00 €	IS0	IS1	34229	
Retrofitting tyre pressure control	86,00 €	7K0	7K1	33459	
Retrofitting seat heater for driving seat	86,00 €	4A0	4A1	348CF	Replace control unit for climate control. Retrofit seat heater elements for the driving seat.
Retrofitting seat heater for driving and passenger seat	86,00 €	4A0	4A3	35B57	Replace control unit for climate control. Retrofit seat heater elements for the driving seat.

Conversion/retrofit Caddy 4 (MY 2016 - 2020)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofitting DAB+	61,00 €	QV0	QV3	35CC2	Replace radio/infotainment system for the new PR number. Please see at the ETKA. Retrofit DAB+ antenna.
Retrofitting cruise control	111,00 €	8T0	8T2	369AE	Retrofitting is only possible with a retrofit kit from Volkswagen Accessories. The retrofit kit is supported by Volkswagen accessories. Please note the accessories ETKA.