

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofit side marking lights (model year 2006)	free	7R2	8F5	3056A	
Removal side marking lights (model year 2006)	61,00 €	8F5	7R2	3057E	
Retrofit side marking lights	free	7R8	8F1	30582	
Removal side marking lights	61,00 €	8F1	7R8	30596	
Retrofit side marking lights	free	7R1	8F5	30C10	
Removal side marking lights	61,00 €	8F5	7R1	30C24	
Retrofit side marking lights without preparation	61,00 €	8F0	8F1	305A6	
Retrofit position lights	61,00 €	6S0	6S3	30605	
Removal position lights	61,00 €	6S3	6S0	30619	
Retrofit 3rd brake light	61,00 €	8R0	8R1	30699	Medium or Highline BSG is a prerequisite
Retrofit 3rd brake light with preparation	free	8R6	8R1	32902	
Removal preparation 3rd brake light	free	8R6	8R0	33267	The preparation for the 3rd brake light must be removed, when a vehicle don't get a 3rd brake light.

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Removal 3rd brake light	61,00 €	8R1	8R0	306A9	
Retrofitting of fog lights	86,00 €	8WA	8WB	3062D	Medium or Highline BSG is a prerequisite
Retrofit fog lights with preparation	free	8WZ	8WB	30645	Medium BSG fitted as standard
Removal of fog lights	86,00 €	8WB	8WZ	30631	
Retrofit bulb failure check	61,00 €	none or GD1	GD0	30A32	After coding, perform control unit reset via self-diagnosis in the instrument cluster
Removal bulb failure check	61,00 €	GD0	GD1	30A46	Exception: All turn indicators due to statutory requirement. After coding, perform control unit reset via self-diagnosis in the instrument cluster
Retrofit parking light circuit	61,00 €	8B0	8B1	306FD	
Removal parking light circuit	61,00 €	8B1	8B0	30708	
Retrofit step light	61,00 €	9N0	9N2	30671	
Removal step light	61,00 €	9N2	9N0	30685	
Retrofit cruise control system with speed limiter (5-Cylinder engine)	111,00 €	8T0	8T1	30734	Installation of accelerator pedal for Shiftmatic gearbox with manual gearbox is mandatory!
Removal cruise control system with speed limiter (5-Cylinder engine)	111,00 €	8T1	8T0	30748	

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofit cruise control system with speed limiter (4-Cylinder engine)	111,00 €	8T0	8T1	319D0	Installation of accelerator pedal for Shiftmatic gearbox with manual gearbox is mandatory! Not possible for Achleitner 4x4
Removal cruise control system with speed limiter (4-Cylinder engine)	111,00 €	8T1	8T0	319CC	
Retrofit 2nd battery	61,00 €	8FA	8FD	30659	Medium or Highline BSG is a prerequisite
Removal 2nd battery	61,00 €	8FD	8FA	3066D	
Retrofit 120 km/h warning	61,00 €	6Y0	6Y1	305E6	After coding, perform control unit reset via self-diagnosis in the instrument cluster
Removal 120 km/h warning	61,00 €	6Y1	6Y0	305FA	After coding, perform control unit reset via self-diagnosis in the instrument cluster
Retrofit headlight washer system	86,00 €	8X0	8X1	306BD	Medium or Highline BSG is a prerequisite
Removal headlight washer system	86,00 €	8X1	8X0	306C1	
Retrofit rear step	61,00 €	QT5	QT9	309B6	Measure is only required with park assist
Removal rear step	61,00 €	QT9	QT5	309CA	Measure is only required with park assist
Retrofit park assist	86,00 €	7X0	7X2	3071C	
Removal park assist	86,00 €	7X2	7X0	30720	

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Removal park assist (rear view camera will be still active)	86,00 €	7X9	7X8	32EEA	
Removal park assist (preparation rear view camera will be still active)	86,00 €	7X4	7X3	32A76	
Retrofit rear view camera	86,00 €	7X0 or 7X2	7X9 or 7X8	32D97	Measure is only required for RSD 4000 or RNS 6000
Retrofit rear view camera	free	7X3 or 7X4	7X9 or 7X8	325BE	Measure is only required for RSD 4000 or RNS 6000
Retrofit tyre pressure monitor	86,00 €	7K0	7K1	31134	After coding, perform control unit reset via self-diagnosis in the instrument cluster
Removal tyre pressure monitor	86,00 €	7K1	7K0	31148	After coding, perform control unit reset via self-diagnosis in the instrument cluster
Retrofit DTCO with preparation	free	9ND	9NH	305BA	After coding, perform control unit reset via self-diagnosis in the instrument cluster - During the preparation, the CAN cable must be connected on the A-pillar! Note Art. 57 B!
Removal DTCO	86,00 €	9NH	9ND	305CE	After coding, perform control unit reset via self-diagnosis in the instrument cluster. Note Art. 57 B!
Removal DTCO for use with blue lights and siren	86,00 €	9NZ	9ND	31584	After coding, perform control unit reset via self-diagnosis in the instrument cluster. Note Art. 57 B!
Retrofit DTCO without preparation	86,00 €	9NA	9NH	305D2	After coding, perform control unit reset via self-diagnosis in the instrument cluster. Note Art. 57 B!
Retrofit electrical 2-driver tachograph with preparation	free	9ND	9NR	308F3	After coding, perform control unit reset via self-diagnosis in the instrument cluster. During the preparation, the CAN cable must be connected on the A-pillar! Note Art. 57 B!
Removal electrical 2-driver tachograph	86,00 €	9NR	9ND	308DB	After coding, perform control unit reset via self-diagnosis in the instrument cluster. Note Art. 57 B!

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Retrofit PSM module	111,00 €	UF0	UF1	307B0	Instructions in Servicenet
Removal PSM module	86,00 €	UF1	UF0	307C4	
Retrofit PSM, terminal strip present	111,00 €	UF3	UF2	307D8	Instructions in Servicenet
Removal PSM, terminal strip present	86,00 €	UF2	UF3	307EC	
Retrofit PSM with preparation but without terminal strip	free	UF4	UF2	307F0	Instructions in Servicenet. During the preparation, the CAN cable must be connected on the A-pillar!
Retrofit PSM with preparation and terminal strip	free	UF5	UF2	3080B	Instructions in Servicenet. During the preparation, the CAN cable must be connected on the A-pillar!
Retrofit tow hitch without preparation	86,00 €	1D0	1D1	3079C	
Retrofit tow hitch with preparation 1M7, Crafter 35	free	1M7 & 0WC	1M0	31099	During the preparation, the CAN cable must be connected on the A-pillar!
Retrofit tow hitch with preparation 1M7, Crafter 50	free	1M7 & 0WF	1M0	3188D	During the preparation, the CAN cable must be connected on the A-pillar!
Retrofit tow hitch with preparation 1M1	free	1M1	1M4	311AC	During the preparation, the CAN cable must be connected on the A-pillar!
Retrofit tow hitch with preparation 1M5	free	1M5	1D1	30788	During the preparation, the CAN cable must be connected on the A-pillar!
Preparation 1D7	free	1D7	1D1	318C9	

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Preparation 1D8	free	1D8	1D1	318DD	
Removal tow hitch 1D1	61,00 €	1D1	1M5	307AC	Control unit must be disconnected from the CAN
Removal detachable tow hitch 1D2	61,00 €	1D2	1M5	3166F	Control unit must be disconnected from the CAN
Removal tow hitch 1M4	61,00 €	1M4	1M1	318B5	Control unit must be disconnected from the CAN
Removal tow hitch 1M0, Crafter 35	61,00 €	1M0 & OWC	1M7	31891	Control unit must be disconnected from the CAN
Removal tow hitch 1M0, Crafter 50	61,00 €	1M0 & OWF	1M7	318A1	Control unit must be disconnected from the CAN
Removal anti-theft alarm	86,00 €	7AQ	7AA	30952	
Retrofit electr. adjustm. Heated exterior mirrors	61,00 €	6XA	6XD	3090E	The door control unit must be renewed acc. to ETKA
Retrofit rear window washing system	61,00 €	8M0	8M1	30AAA	Medium or Highline BSG is a prerequisite
Removal rear window washing system	61,00 €	8M1	8M0	30ABE	
Retrofit heated rear window	86,00 €	4HG	4HH	306D5	Medium or Highline BSG is a prerequisite

Conversion/retrofit Crafter (MY 2006 - 2017)

Designation	Purchase cost for importer	PR no		Measure Code	Remark
		Pre-condition	New		
Removal heated rear window	86,00 €	4HH	4HG	306E9	
Retrofit retarder	free	1H5	100	3075C	Is only possible with the 1H5 preparation! PSM coding additionally required. For instructions, see Servicenet.
Removal retarder	111,00 €	100	1H5	30760	PSM must be reset!
Retrofit Outside Temperatur Display	209,00 €	9Q0	9Q9	32251	Changeover from temp. to speed is performed using M key with the ignition switched on > 1 sec
Retrofit automatic window lifting	61,00 €	4R4	4R1	32340	
Retrofit 2nd evaporator	86,00 €	9AP	9AS	32CE4	Air-condition controler must be replaced
Retrofit rear speaker	86,00 €	8RS	8RT	3332A	Only for RSD 4000 and RNS 6000
Retrofit seat heater on the passenger side	86,00 €	4A1	4A3	3650E	Only possible if the vehicle is already equipped with seat heating on the driver side.